ANNEX 2

Sums emboldened nave been ordered/action		1	1			T
		Programme		New	Totals	
	Savings	Changes	Requested	Items		Admin & Property brief comments
		Over Time	,	_		
	£	£	£	£	£	
Leisure Services						
Leisure Services						
Angel Centre						
Refurbishment of lift				17,000		New item
Provision of external handrail				1,500		New item
Plant renewals			2.000	1,000		Increased based on expenditure to date
Renew fire alarm/emerg light batteries		3,000	_,000			Reprogrammed from 10/11 & increased
Transmine diaminomong light butteries		3,000	3,000			following survey
Window/door repairs		2,030	3,000			Reprogrammed from 10/11
Servicing - air conditioning/handling		2,030	7,000			Increased based on expenditure to date
Duct cleaning			7,000	3,000		New item
•			2 500	3,000		1
Response maintenance general	0	E 020	3,500 15,500	21,500	42.020	Increased based on expenditure to date
	0	5,030	15,500	∠1,500	42,030	
Tonbridge Farm Pavillion						
Gas main investigations		2,000				Reprogrammed from 10/11
IEE testing		600				Reprogrammed from 10/11 & increased
TEE lesting		800	4 700			
	0	2.600	1,700 1,700	0	4 200	based on expenditure to date
	0	∠,600	1,700	U	4,300	
Larkfield Leisure Centre						
Renew handrails to pools		10,000				Reprogrammed from 10/11 & decreased
Nenew nationalis to pools	(10,000)					based on expenditure to date
Reline/refill filters	(10,000)		1,000			
		4 000	1,000			Increased following survey
BMS system maintenance/upgrade		1,880		0.500		Reprogrammed from 10/11
Sauna seating renewal			2 000	2,500		New item
Window/door repairs	(4.400)		3,000			Increased based on expenditure to date
Barrel vault roof maintenance	(1,400)			0.55		Reduced based on expenditure to date
Drain and gully cleaning/jetting				800		New item
Duct cleaning			7,500			New item
	(11,400)	11,880	11,500	3,300	15,280	

	Initial	Programme	Revisions	New	Totals	
	Savings	Changes	Requested	Items		Admin & Property brief comments
		Over Time	By Services			
	£	£	£	£	£	
Tonbridge Swimming Pool						
Main roof tile repairs	(25,000)					Deleted from the plan
Ozone module repairs				4,300		New item
Pool tile repairs			1,500			Increased following survey
Reline/refill filters		1,000				Reprogrammed from 10/11
Servicing - pool plant			1,500			Increased based on expenditure to date
BMS system maintenance/upgrade		1,880				Reprogrammed from 10/11
Pool hall lighting maintenance			2,500			Increased based on expenditure to date
External decoration			3,000			Increased following survey
Servicing - fire alarm/emerg lighting			3,500			Increased based on expenditure to date
Drain and gully cleaning/jetting			1,700			New item
Duct cleaning			4,500			New item
G	(25,000)	2,880	18,200	4,300	380	
Racecourse Sports Ground						
Predecoration repairs	(500)					Reprogrammed to 13/14
External decoration	(2,000)					Reprogrammed to 13/14
Bridge testing	(2,000)					Reduced based on expenditure to date
2.1.2.30 (30 (1.1.1)	(4,500)		0	0	(4,500)	
Poult Wood Golf Centre Clubhouse						
External decoration			2,000			Increased following survey
Servicing - air conditioning/handling			2,000			Increased lonowing survey Increased based on expenditure to date
Servicing - all conditioning/handling	0	0		0	4.000	increased based on expenditure to date
	0	U	4,000	U	4,000	

	Initial	Programme		New	Totals	
	Savings	Changes	Requested	Items		Admin & Property brief comments
		Over Time	By Services			
	£	£	£	£	£	
Poult Wood Golf Centre Maintenance Building	5					
Servicing - roller shutters	(500)					Reduced based on expenditure to date
-	(500)	0	0	0	(500)	
Pleasure Grounds & Open Spaces						
Haysden - predecoration repairs	(200)					Reprogrammed to 13/14
Haysden - external decoration	(2,000)					Reprogrammed to 13/14
Haysden - internal decoration - general	(250)					Reprogrammed to 13/14
L/Lakes - predecoration repairs	(400)					Reprogrammed to 13/14
L/Lakes - external decoration	(3,000)					Reprogrammed to 13/14
	(5,850)	0	0	0	(5,850)	
Tonbridge Cemetery						
Chapel stonework repairs			5,500			Increased based on expenditure to date
Cemetery wall repairs				5,000		New item
Response maintenance general				500		New item
	0	0	5,500	5,500	11,000	
Tonbridge Castle Gatehouse						
Lighting controller overhall		3,000				Reprogrammed from 10/11
Stonework repairs				9,300		New item
•	0	3,000	0	9,300	12,300	
					·	
Leisure Services Sub-total	(47,250)	25,390	56,400	43,900	78,440	

ANNEX 2

Sums emboldened have been ordered/actioned		1	1			
	Initial	Programme		New	Totals	
	Savings	Changes	Requested	Items		Admin & Property brief comments
		Over Time	By Services			
	£	£	£	£	£	
Health & Housing						
Public Toilets						
Floor/drainage improvement		6,000				Reprogrammed from 10/11 & deleted
	(6,000)					from the plan
Ventilation improvements		2,750				Reprogrammed from 10/11 & deleted
•	(2,750)					from the plan
Lighting improvements		4,000				Reprogrammed from 10/11 & deleted
	(4,000)					from the plan
Security improvements	,	800				Reprogrammed from 10/11 & deleted
	(800)					from the plan
Window/door repairs	, ,	2,340				Reprogrammed from 10/11
Health & Housing Sub-total	(13,550)	15,890	0	0	2,340	, -
Corporate Services						
Gibson West						
Refurbishment of wing toilets		25,000				Reprogrammed from 10/11 & increased
Ğ		,	3,300			based on expenditure to date
Servicing - intruder alarm system	(500)		·			Reduced based on expenditure to date
Servicing - access system	,		6,000			Increased based on expenditure to date
Servicing - lightning protection	(500)					Reduced based on expenditure to date
Servicing - cistermisers	()		1,700			Increased based on expenditure to date
Servicing - gas ext system			200			Increased based on expenditure to date
Servicing - disabled accessible facility	(600)					Reduced based on expenditure to date
Gas soundness test	(= 3-)			300		New item
	(1,600)	25,000	11,200	300	34,900	
	(, , , , , ,	, , , , ,	,		,	
		I			ı	ı

sums emboldened have been ordered/actioned	Initial	Programme	Revisions	New	Totals	
	Savings	Changes	Requested	Items		Admin & Property brief comments
			By Services			, ,
	£	£	£	£	£	
Tonbridge Castle						
First floor kitchen area refurbishment	(2,500)					Reprogrammed to 12/13
Predecoration repairs	(4,000)					Reprogrammed to 12/13
External decoration	(17,700)					Reprogrammed to 12/13
Carpet/floor laying - public areas		10,000				Reprogrammed from 10/11
Servicing - disabled accessible facility	(1,900)					Reduced based on expenditure to date
	(26,100)	10,000	0	0	(16,100)	
Gibson East						
Footpath construction to protect pedestrians	(5,000)					Deleted from the plan
Servicing - intruder alarm system	(300)					Reduced based on expenditure to date
Servicing - Windcatchers	(000)		3,000			Increased following survey
Gas soundness test			3,000	300		New item
	(5,300)	0	3,000	300	(2,000)	
Land Review						
Castle Lodge - IEE testing		1,000				Reprogrammed from 10/11
River Walk - IEE testing		1,000				Reprogrammed from 10/11
ILL tooking	0	2,000	0	0	2,000	1.56.53.3
Corporate Services Sub-total	(33,000)	37,000	14,200	600	18,800	
Grand Total as at 07/09/11 £	(93 800)	78,280	70,600	44,500	99,580	