



©Crown Copyright and database right 2018. Ordnance Survey 100019238.

Poor footway width and levels

No room for a bus shelter due to access way and the length of the bus layby

The required length of the bus layby would block the access way.

0	17/05/18		DLP		JW
Rev	Revision Date	Purpose of revision	Drawn	Checked	Approved
This drawing is not to be used in whole or part other than for the intended purpose and project as defined on this drawing. Refer to the contract for full terms and conditions.					

Project
High Street, Tonbridge.

Drawing title
Traffic Mangement Improvements

OPTION 2

Kent County Council
kent.gov.uk

Kent County Council
Ashford Highway Depot
Herwood Industrial Estate
Ashford TN24 8AD
Tel: 03000 418181

Drawing status		
Scale	at A4	Do not scale
Drawing number		Rev 0